Title	Demonstrate knowledge of faults for fibreboard packaging		
Level	3	Credits	10

Purpose	People credited with this unit standard are able to: identify board faults in the fibreboard packaging industry, and define diagonal warp and describe its causes.
Classification	Fibreboard Packaging > Fibreboard Packaging Production

Available grade	Achieved	

#### **Guidance Information**

- Candidates must follow any applicable and recognised codes of practice, and documented workplace health, safety, and environmental procedures for personal, product, workplace health, safety, and environmental matters, and the obligations required under current law including the Health and Safety in Employment Act 1992 and its subsequent amendments.
- 2 Definition Workplace practices refer to the documented procedures for the equipment and/or workplace.

# Outcomes and performance criteria

### **Outcome 1**

Identify board faults in the fibreboard packaging industry.

# Performance criteria

1.1 Warp types are identified from samples.

Range up warp, down warp, diagonal warp, S warp.

1.2 Faults are identified from photographs or physical samples.

## Range

depending on workplace practices and equipment configuration faults may include but are not limited to — blisters, wrinkles, cockles, splices, slot lines, edge fluff outs, other delamination or poor adhesion whether localised or extensive, cut or fractured or crushed corrugations, low flutes, leaning flutes, highs and lows, other non-specified damage or deformation to corrugations, indentations, scuff marks, dry streaks, wash-boarding, splits at crease lines, other damage to liner papers, unslit board, untrimmed board, badly trimmed board, misalignment, failure of board to bend cleanly at crease lines, warp types, splices in board, liner inside out; evidence is required for six faults.

- 1.3 The conditions 'wet board' and 'green bond' are defined in terms of strength.
- 1.4 The presence of fibre tear in manufactured board is identified in accordance with workplace practices.

#### Outcome 2

Define diagonal warp and describe its causes.

## Performance criteria

- 2.1 Diagonal warp is defined in terms of the axis of the warp running diagonally across the board.
- 2.2 Conditions of reel stock that might cause diagonal warp to occur are described.

Range includes but is not limited to – fibre orientation, slack edges in reel, paper grammage or calliper not within specification.

2.3 Tension inequalities that might cause diagonal warp are described.

Range includes but is not limited to – slack edges in reel, reel stands out of line, wrap arms not level, rollers not parallel, misalignment of top belt, uneven pressure roller pressures.

2.4 Moisture variations that might cause diagonal warp are described.

Range includes but is not limited to – varying moisture levels across the paper width, uneven adhesive application, uneven heat application.

2.5 Equipment faults that might cause conditions leading to diagonal warp are described.

Range includes but is not limited to – reel stands, wrap arms, rollers, top belt.

Replacement information	This unit standard was replaced by skill standard 40328.	
	This unit standard replaced unit standard 3762 and unit standard 10160.	

This unit standard is expiring. Assessment against the standard must take place by the last date for assessment set out below.

Status information and last date for assessment for superseded versions

Process	Version	Date	Last Date for Assessment
Registration	1	20 September 2012	31 December 2027
Review	2	28 November 2024	31 December 2027

Consent and Moderation Requirements (CMR) reference	0005

This CMR can be accessed at <a href="http://www.nzqa.govt.nz/framework/search/index.do">http://www.nzqa.govt.nz/framework/search/index.do</a>.