Title	Assist press operator for dry offset printing		
Level	3	Credits	15

Classification	Printing > Dry Offset	
Available grade	Achieved	
Drovomicitos	Unit 240 Demonstrate knowledge of onfo weaking proctions in	

Prerequisites	Unit 340, Demonstrate knowledge of safe working practices in the print industry, or demonstrate equivalent knowledge and skills.

#### **Guidance Information**

- 1 Legislation, regulations and/or industry standards relevant to this unit standard include but are not limited to the:
  - Hazardous Substances and New Organisms Act 1996;
  - Health and Safety at Work Act 2015;
  - Privacy Act 2020:
  - Resource Management Act 1991.

Any new, amended or replacement Acts, regulations, standards, codes of practice, guidelines, or authority requirements or conditions affecting this unit standard will take precedence for assessment purposes, pending review of this unit standard.

## 2 Definitions

Job documentation refers to the documentation that is used in the workplace that contains the instructions and requirements for a particular production job. This may include but is not limited to workplace orders, production orders, workplace specifications, samples, lay cards.

Job requirements refer to specific requirements for the print job at hand. These requirements may or may not be covered in the job documentation and may include special instructions, quality requirements expected by the customer, and/or production standards as set down by the print workplace.

Press requirements refer to the specific requirements for the press being operated as set out in the operating manual or in accordance with workplace practices.

Workplace procedures refer to organisation policies and procedures that are documented in memo, electronic, or manual format and available in the workplace. They may include but are not limited to – standard operating procedures, site specific procedures, site safety procedures, equipment operating procedures, quality assurance procedures, product quality specifications, manufacturer's requirements, references, approved codes of practice, housekeeping standards, environmental considerations, on-site briefings, supervisor's instructions, and procedures to comply with legislative and local body requirements relevant to the print sector.

3 Assessment information

All production tasks in this unit standard are to be carried out under the direction of the press operator.

Evidence presented for assessment against this unit standard must be consistent with safe working practices and be in accordance with applicable service information, workplace procedures and legislative requirements.

# Outcomes and performance criteria

#### Outcome 1

Follow safety requirements for the press being used.

## Performance criteria

- 1.1 Follow press start up and shut down procedures.
- 1.2 Demonstrate emergency procedures for the press.
- 1.3 Describe and follow hazard control measures in the workplace.
- 1.4 Identify and report hazards or potential hazards in the workplace.

#### Outcome 2

Check documentation and confirm requirements for the job are available.

#### Performance criteria

- 2.1 Check job documentation to ensure that all specifications for the process being undertaken are complete and report any discrepancies.
- 2.2 Check required job components against the job documentation and confirm their availability with the press operator.
- 2.3 Confirm equipment is available, as advised by the press operator.

#### **Outcome 3**

Handle and store substrates used in dry offset printing.

NZQA unit standard 33185 version 1
Page 3 of 5

#### Performance criteria

3.1 Describe substrates in terms of their characteristics.

Range

may include but is not limited to – grammage, calliper, width, coatings, pH, bulk value, opacity, transparency, absorbency, strength, smoothness, colour, finish, receptivity, flexibility, size, dimensional stability, job suitability, grain direction, texture, surface finish, dye migration, post print migration.

3.2 Handle and store substrates in accordance with press operator's instructions.

Range

may include but is not limited to -

handling – clean working environment, clean hands, transporting methods, stacking, knocking up, grain direction, working side, avoidance of damage to substrate, affinity to ink, avoidance of

personal injury;

storage - light, temperature, air flow control, relative humidity, age

(substrate rotation), ease of access.

3.3 Confirm substrate quantity issued against job documentation.

#### **Outcome 4**

Identify and use additives and chemicals.

Range

may include but is not limited to – ink additives, fountain additives, driers, water treatment agents, water, alcohol or alcohol substitutes, cleaners, desensitisers, deletion fluids.

#### Performance criteria

- 4.1 Identify additives and chemicals used in the workplace.
- 4.2 Use additives and chemicals in accordance with press operator's instructions to meet press and job requirements.

## Outcome 5

Assist in make ready and printing tasks.

#### Performance criteria

- 5.1 Confirm plates or sleeves are correct for the job with the machine operator before proceeding to secure them on the machine.
- 5.2 Mount plates square, centred, and tensioned to meet press requirements.
- 5.3 Add correct amount of ink to duct or reservoir to achieve required colour consistency.
- 5.4 Use plate cleaners and desensitisers.

NZQA unit standard 33185 version 1
Page 4 of 5

5.5 Add ink to the ducts and/or reservoirs in the correct amount to suit both the image carrier and the run length.

Load substrate into press, position in accordance with job requirements, and advise press operator that press is set and loaded.

Range may include but is not limited to –

loading - manual, lifting gear, press and job requirements;

position – grip and side lays, registration.

5.7 Identify or report any faults found while loading substrate.

Range faults may include but are not limited to – damaged corners and

edges, wavy edged stock, tight edged stock, foreign matter, grip,

dimensional distortion, marking.

5.8 Unload substrate safely, and identify and report any defects to the press operator.

Range defects may include but are not limited to – marking, mis-

registration, bad stacking, drying, adhesion, splitting, crushing,

drying system faults, inking system faults.

#### **Outcome 6**

Undertake post press tasks.

## Performance criteria

- 6.1 Check quantity printed against job documentation before wash up is commenced or image carrier is removed from cylinder, and rectify or report any discrepancies in quantity.
- 6.2 Complete job documentation.
- 6.3 Carry out other post-press tasks as required by the job documentation.

Range may include but is not limited to – prepare for forwarding to next

process, labelling, substrate handling, filing image carriers, quality

assurance (QA) requirements.

6.4 Follow waste control procedures.

Range recyclable waste, non-recyclable waste, security waste.

**Replacement Information** This unit standard replaced unit standard 19462.

NZQA unit standard 33185 version 1
Page 5 of 5

Planned review date 3	31 December 2027
-----------------------	------------------

Status information and last date for assessment for superseded versions

Process	Version	Date	Last Date for Assessment
Registration	1	30 March 2023	N/A

Consent and Moderation Requirements (CMR) reference	0013
---	------

This CMR can be accessed at <a href="http://www.nzqa.govt.nz/framework/search/index.do">http://www.nzqa.govt.nz/framework/search/index.do</a>.

## Comments on this unit standard

Please contact Hanga-Aro-Rau Manufacturing, Engineering and Logistics Workforce Development Council <u>qualifications@hangaarorau.nz</u> if you wish to suggest changes to the content of this unit standard.