

Title	Make basic windsurf repairs		
Level	3	Credits	16

Purpose	People credited with this unit standard are able to: recognise nature of repair required; and make basic windsurf repairs.
----------------	--

Classification	Outdoor Recreation > Windsurfing
-----------------------	----------------------------------

Available grade	Achieved
------------------------	----------

Guidance Information

- 1 All activities must comply with relevant environmental, legislative, and/or regulatory requirements set out in the *New Zealand Environmental Care Code*, Health and Safety in Employment Act 1992, Injury Prevention, Rehabilitation, and Compensation Act 2001, and their subsequent amendments. The *New Zealand Environmental Care Code* is available from the Department of Conservation, Head Office, PO Box 10420, Wellington, <http://www.doc.govt.nz/>.
- 2 There are minimum assessor requirements for assessment against this unit standard. The details of these requirements are available on the Sfrito website <http://www.sfrito.org.nz>.

Outcomes and performance criteria

Outcome 1

Recognise nature of repair required.

Performance criteria

- 1.1 Description of boards identifies construction materials, construction techniques, and board function.
- 1.2 Participant needs are analysed in terms of repair requirements.
- 1.3 Participants are advised of repair options available to meet their needs.

Range on site repair, participant repair, temporary repair, permanent repair, send to expert.
- 1.4 Materials advised by participant for repair match nature of repair.

Outcome 2

Make basic windsurf repairs.

Range all repairs meet requirements of company practice.

Performance criteria

2.1 Repairs to minor piercing of outer skin of board are watertight and meet manufacturer's requirements.

Range scratch filling, patching, dent repair.

2.2 Universal joint repair functions as new, and chemical fastener is used to ensure that locks cannot come undone.

2.3 Seized mast track is freed.

2.4 Boom clamp repair is watertight and functional.

2.5 Batten repairs ensure that the batten is functional.

2.6 Worn boom covering is completely scraped off prior to replacement being glued on.

2.7 All repair materials used are compatible with board type.

2.8 Corroded or worn parts are identified and replaced, and customer advised.

This unit standard is expiring. Assessment against the standard must take place by the last date for assessment set out below.

Status information and last date for assessment for superseded versions

Process	Version	Date	Last Date for Assessment
Registration	1	27 June 1996	31 December 2023
Revision	2	14 February 2000	31 December 2023
Revision	3	22 October 2004	31 December 2023
Rollover and Revision	4	26 January 2007	31 December 2023
Review	5	16 December 2021	31 December 2023

Consent and Moderation Requirements (CMR) reference

0102

This CMR can be accessed at <http://www.nzqa.govt.nz/framework/search/index.do>.